


RISK CONTROL CONSULTING

Cold Stress

Working under cold conditions can lead to various injuries or health effects, which are collectively known as cold stress. Construction workers may experience cold stress when working:

- Outdoors on a cold day.
- In a refrigerated room.
- In an unheated building.
- In cold water, rain, or snow.
- While handling cold objects or materials.





HAZARDOUS EFFECTS

The hazardous effects of cold on the body may include dehydration, numbness, shivering, frostbite, immersion foot (trench foot), and hypothermia. Hazards associated with cold stress are categorized into systemic and local effects.

Local Effects = Impact the part of the body where the exposure to cold is the greatest.

Examples include: numbness, frostbite and immersion foot*

*Immersion foot is the result of the skin's having been exposed too long to cold and dampness. Immersion foot can result in swelling, tingling, itching, loss of skin, or skin ulcers.

Systemic Effects = Impact more than just the local area and can affect the whole body.

Examples include: dehydration and hypothermia

Hypothermia is the most serious effect of cold stress. Once the body loses the ability to maintain its normal temperature, the body temperature lowers, and other symptoms such as violent shivering, slow or slurred speech, confusion, hallucinations, a weak and irregular pulse, or unconsciousness occurs.

WHO IS AT RISK?

Certain people are more susceptible than others to cold stress. People who are not physically fit, have a chronic illness, drink alcohol or take drugs (including prescription drugs), are wet or damp from work or weather, are



RISK CONTROL CONSULTING

fatigued, are exposed to vibration from tools, don't wear the right clothing, or are not used to working in cold have a higher risk from cold stress.

HOW CAN YOU RECOGNIZE COLD STRESS?

Shivering is the body's response to cold stress and serves as a protection mechanism by increasing the rate of metabolism. Be on guard for cold stress if workers are shivering because it's a good sign of cold stress and possible hypothermia. Subjective responses of workers provide a good tool for recognizing cold stress in the workplace. Worker behaviors that may indicate cold stress exposures include seeking warm locations, adding layers of clothing, or increasing the work rate.

• If there is a noticeable drop in manual dexterity for workers, local cold stress may be occurring. Manual dexterity decreases with cold, which could result in safety hazards to the worker and coworkers.

PREVENTING COLD STRESS

Employers can help protect workers from cold stress by providing training, controlling temperature and wind when possible by using heaters and windbreaks, rotating workers in cold jobs so that no one is exposed too long, scheduling work at warmest times, encouraging self-pacing and extra breaks if necessary, establishing a buddy system, and keeping first aid supplies and equipment available.

Equally important, employees can do their part to prevent cold stress. Proper insulation and good ventilation is critical for clothing worn during cold stress exposures. Better insulation is achieved by layering clothes rather than by wearing just one warm garment. Layering allows a person to add or remove layers to adjust for different insulation needs during the work period.

Note that the insulation quality of clothing may be greatly decreased by moisture. Thus, water vapor permeability is also important. A waterproof shell may not allow sweat to escape. A water repellent shell may keep a worker warmer. Seek warm locations during breaks and replace lost fluids with warm, sweet, non-caffeine-containing drinks to avoid dehydration. By taking the necessary precautions, employers and workers together can minimize the potential for cold stress.

This Tribal First Risk Control Consulting fact sheet is not intended to be exhaustive. The discussion and best practices suggested herein should not be regarded as legal advice. Readers should pursue legal counsel or contact their insurance providers to gain more exhaustive advice. For more information on this topic, please contact Tribal First Risk Control Consulting at (888) 737-4752 or riskcontrol@tribalfirst.com.